UNCLASSIFIED

AD 295 474

Reproduced by the

ARMED SERVICES TECHNICAL INFORMATION AGENCY
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

SPRINGFIELD ARMORY

SPRINGFIELD, MASSACHUSETTS

RESEARCH AND DEVELOPMENT

295 474

Report: 8A-TR20-2313

Date: 1 August 1962

<u>Nesort Title:</u> Investigation of Packaging Methods and Submethods with Volatile-Corrosion-Inhibitor Treated Materials

uthor: oxwed Pa

Chem Bagr

Approved:

H. 'Y. MANTHUME

Chief, Mes and Dev Div





The findings in this report are not to be construed as an official Department of the Army position.

Copies available at Office of Technical Services \$1.25

ASTIA AVAILABILITY NOTICE. Qualified requesters may obtain copies of this report from ASTIA.

Report: SA-TR20-2313

Date: 1 August 1962

Report Title: Investigation of Packaging Methods and Submethods

with Volatile-Corrosion-Inhibitor Treated Materials

uthor: grace whiteh

G. PRIBUTSKY

Chem Engr

Approved:

H. F. HAWTHORNE

Chief, Kes and Dev Div

Preparing Agency: Springfield Armory, Springfield, Mass.

This technical report, to the extent known, does not contain any patented material, trade secrets, copyrighted and/or copyrightable material, trade marks or trade names.

NONLIMITATION ON REPRODUCTION AND DISTRIBUTION. This is a nonlimited distribution report. Initial distribution of the report has been made in accordance with the attached distribution list. Reproduction and/or distribution by any installation or agency is authorized.

DISPOSITION: Destroy. Do not return.

ABSTRACT

An investigation was made to evaluate the suitability of using various submethods with volatile-corrosion-inhibitor-treated materials in the packaging of small arms components. Packages were stored under two conditions: (1) in an outdoor shed to simulate minimum warehouse storage and (2) in a static humidity cabinet to simulate tropic storage. Hest-seelable polyester film with volatile-corrosion-inhibitor innerwrap provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that packaging submethods other than those specified in MIL-I-8574 can be satisfactorily used with VCI preservatives. Test procedures are described and results given.

CONTENTS

	Page
Subject	1
Objectives .	2
Summary of Conclusions	2
Recommendations	2
Introduction	3
Procedures	3
Results and Discussion	6
Vial Packs, Humidity Cabinet Vial Packs, Outdoor Storage Shed Heat-sealable Polyester Film, Humidity Cabinet Heat-sealable Polyester Film, Outdoor Storage Shed Submethod 1C-1, Humidity Cabinet Submethod 1C-1, Outdoor Storage Shed Submethod 1C-2, Humidity Cabinet Submethod 1C-2, Outdoor Storage Shed Submethod 1C-5, Humidity Cabinet Submethods 1C-5 and 1C-5 (Modified), Outdoor Storage Shed Submethod 1A-8, Humidity Cabinet Submethod 1A-8, Outdoor Storage Shed Submethod 1A-8, Outdoor Storage Shed Submethod 1A-15, Humidity Cabinet Submethod 1A-15, Outdoor Storage Shed	6 6 7 8 8 8 9 10 10 11 11 12 12
Conclusions	12
Appendices	
A - Tables (14) B - Figures (8 Photographs) C - Distribution	15 29 38

SUBJECT

Investigation of packaging methods and submethods in which volatilecorrosion-inhibitor treated materials were used in a static humidity cabinet and in an outdoor storage shed.

OBJECTIVES

The objective of this study was to investigate the packaging of small arms components with P-9 and P-18 preservatives under storage conditions of both an outdoor shed and a static humidity cabinet. Various methods and submethods described in Specification MIL-P-116 were used in this investigation.

SUMMARY OF CONCLUSIONS

Volatile corrosion inhibitor material was used with various packaging submethods and materials in the static humidity cabinet and in the outdoor storage shed for tests of one and three years, respectively. These testing conditions were used to simulate indeterminate storage conditions encountered with Level A preservation and packing.

Submethod 1A-8 and 1A-15, as well as a polyester film laminated on both sides with polyethylene, provided satisfactory protection in the humidity cabinet when volatile-corrosion-inhibitor innerwrap was used. Also Submethod 1C-2 provided some protection under identical conditions. Clear polystyrene vials were not satisfactory for either the humidity cabinet or the outdoor storage shed. Submethod 1C-1 1C-5, and 1C-5 (Modified), did not provide satisfactory protection for the components.

The effectiveness of the volatile corrosion inhibitor in the various packs could not be evaluated in the outdoor storage shed since most of the packs with and without volatile corrosion inhibitor were satisfactory.

RECOMMENDATIONS

- 1. Accelerated tests <u>not</u> be used as an absolute criterion for evaluating various methods of packaging as set forth in MIL-P-116 (particularly, if volatile corrosion inhibitors are used).
- 2. Various materials be investigated to evaluate the maximum WVTR (water-vapor transmission rate) value for use with volatile corrosion inhibitor material under long-term indeterminate storage conditions.

RECOMMENDATIONS - Continued

3. Transmission rates of VCI vapors be established for the various flexible films to provide complete information for the most efficient use of this type of packaging material.

I. INTRODUCTION

The use and application of a volatile-corrosion-inhibitor type of preservative, P-18, in accordance with MIL-I-8574 specifically limits the use of MIL-I-3420 material to waterproof-vaporproof barrier materials for Level A protection. Greaseproof and/or waterproof materials conforming to Methods 1 and 1C of MIL-P-116 were investigated with MIL-I-3420 material to determine whether these packaging methods could be satisfactorily utilized for specific small arms components at a Level A protection.

These components had a manganese phosphate metal finish with a P-9 preservative. The protective coating method, when combined with a P-18 preservative, appeared to lend itself to a lower protective packaging level. The individually packaged components were evaluated in a static humidity cabinet and in an outdoor storage shed, as unit packs, and without the added protection afforded by intermediate packs.

II. PROCEDURE

Expendable MI rifle components consisting of apertures, harmer springs, housings, harmer spring plungers, trigger pins, extractors, butt swivels, housing rear sight covers, trigger housings, latch clips, front swivels, catch operating rods, followers, arm followers, and firing pins selected for this investigation. These components were vapor-cleaned with trichlorethylene and then processed with finish 5.3.1.2 of Military Standard 171. The components were grit-blasted, coated with manganese phosphate, and given a supplementary oil treatment with MIL-L-644 preservative oil.

An outdoor storage shed and a static humidity cabinet were utilized as testing areas for this investigation.

The outdoor storage shed was located on the roof of Springfield Armory Laboratory. This storage shed was a triangular wooden structure approximately 5 feet high, 3 feet deep at the base, and 6 feet wide (Figure 1). Three hinged, overlapping steel doors on each side provided some protection against the direct exposure to extreme weather conditions.

PROCEDURE - Continued

This type of outdoor exposure afforded a good test for evaluating packaging materials since it provided more severe test conditions than minimum warehouse storage.

The static humidity cabinet used in this investigation was approximately 2-3/4 feet high, 2-1/3 feet wide, and 9-1/3 feet long. The temperature maintained in the cabinet throughout the test was 100°F ±5°F with the relative humidity controlled at 95% - 100%.

The submethods investigated were divided into three groups: The first group investigated included containers made of water-proof-vaporproof material that consisted of IA-8 and IA-15 submethods. The second group included containers of greaseproof and/or waterproof barriers that consisted of submethods IC-1, IC-2, IC-5, and a polyester film laminated with polyethylene which was considered as a IC-1 submethod. The third group included Method 1 unit packs that consisted of a clear polystyrene vial with a snap-on polyethylene cover and a modified IC-5 submethod. The modification consisted of the taping of only the closure of the fiberboard box.

The test components were packaged with VCI material conforming to MIL-I-3420, Type I, in various containers. Approximately half of each group was stored in a static humidity cabinet and the remaining half was stored in an outdoor shed. The submethod used for the individual components was determined by the suitability of the submethod to the unit pack.

Approximately two to three control packs were prepared containing selected M1 components. These components were cleaned and processed in a similar manner as outlined in cleaning process C-7 of MIL-P-116 followed by finish 5.3.1.2 of Military Standard 171. These packs did not have VCI material. Approximately two to three packs were stored in the outdoor shed and also in the static humidity cabinet.

The packs were checked monthly in the static humidity cabinet for 12 months with particular concern for the condition of the unit pack, mold growth, condition of the seals, and corrosion-resistant effects by the VCI materials. The various unit packs stored in the outdoor shed were similarly checked monthly for the first 18 months after which they were stored for an additional 18 months and then checked for effects of 36 months outdoor storage. The unit packs were checked sporadically during the last 18 months in the outdoor storage shed.

PROCEDURE - Continued

The control unit packs which did not have VCI were similarly checked at the same time as the test packs in both the static humidity cabinet and in the outdoor storage shed. The control packs, however, were prepared and stored in the respective test apparatus approximately 3 weeks after the start of the test. These controls were used to provide a yardstick with which to evaluate the final results and did not serve as the ultimate criteria for comparative evaluation.

The first unit package investigated was a vial container made of transparent polystyrene with a snap-on polyethylene cap. The vial was approximately 1 inch in diameter and 2 inches in height. Initial examination of this type of container indicated that it may be utilised as a Method 1 pack which in addition could provide an efficient nondestructive check on the condition of the packaged component.

The second type of packaging material was that of heat-scalable polyester film. This material which was scaled on all four sides provided a transparent submethod IC-1. This transparent property of the heat-scalable polyester film provided ideal nondestructive inspection conditions.

The third type of unit package investigated was a sealed water-proof-vaporproof bag, as specified in submethod IA-8 of MIL-P-116, with a barrier material conforming to MIL-B-131, Class 2.

The submethod 1A-15 of MIL-P-116 was investigated with the following materials. This waterproof-vaporproof container-bag submethod was made of slightly different materials. One group of submethod 1A-15 was made of a paperboard container in accordance with Specification PPP-B-566 and covered with MIL-B-131B Class 2 berrier material. The second group of submethod 1A-15 was made of fiberboard boxes conforming to Specification PPP-B-636. The individual containers were taped with PPP-T-76 material and the overwrap bag was made of MIL-B-131 Class 1 material.

The greaseproof-waterproof sealed bags used for submethod 1C-1 were fabricated from MIL-B-121A, Grade A, Type 2, Class 1, material.

The materials used for submethod 1C-2 consisted of a paper board container conforming to Specification PPP-B-566 with the waterproof barrier material conforming to Specification MIL-B-13239A, Grade A, Type B-2, Class 2.

PROCEDURE - Continued

The final submethod investigated was 1C-5. The containers were fabricated from fiberboard material PPP-B-636 into boxes 4" x 4" x 4". The sides and the flaps were sealed with PPP-T-76 tape.

A slight modification of this 1C-5 submethed was made by partially taping the fiberboard box at the flaps or closures. This deviation changed the classification of the pack to a Method 1.

The various unit packs are identified in Figure 2.

III. RESULTS AND DISCUSSION

a. Vial Packs in Humidity Cabinet - Table 1

After one month's exposure in the humidity cabinet, all packs with VCI liners contained a slight amount of moisture indicating the poor seal made by the polyethylene cap. The apertures with VCI rusted after 1 month's exposure; whereas, the hammer spring housings rusted after 4 months' exposure. The moisture content increased in the vials until there was approximately 1/8 inch of water, inside, after 6 months' exposure. The test was terminated after 6 months' exposure (Figure 2).

The control packs exhibited rust on the trigger pins after the third inspection check. However, since the control packs were not placed in the respective testing areas at the same time as the other packs, this represented a little more than 2 months' exposure. After the fourth inspection check, all the control packs rusted.

It is apparent that the VCI did not provide the added corrosion-resistant protection for the components under such adverse conditions. In addition, after 2 to 3 months' storage in the humidity cabinet, the polystyrene vials exhibited cracking. This container was not satisfactory for storage under abnormally wet conditions.

h. Yial Packs in Outdoor Storage Shed - Table 2

The vial packs with VCI were satisfactory; only one of five samples exhibited rust. One hammer spring housing had a very small rust spot. However, this condition resulted after 35 months' exposure.

The control vials, on the other hand, started to rust after 23 months' exposure. At that time, three of four vials had slight rust. This rust condition continued until the end of the 3-year test period. Three of the four control packs contained components on which the rust varied from light to moderate.

Hairline cracks approximately 1/8 inch long appeared on the vials after 8 months' exposure. Cracks progressed approximately 1/4 inch to 1/2 inch long in 20 months. At the end of the 3-year test period, all vials had cracks of various sizes.

The poor aging properties of polystyrene was evidenced by the crased surface. The vial packs with VCI had very slight rust on only one of five packs; whereas, the control vial packs had rust on three of the four packs. The VCI appeared to provide beneficial corrosion-resistant properties for the components during the test period.

c. Heat-sealable Polyester Film in Humidity Cabinet - Table 3

After exposure of 1 month in the humidity cabinet, one of the polyester packs with VCI had leaked because of a poor seal. As a result, the inclosed component, a butt swivel, started to rust. No moisture was observed in any polyester pack after the first month. However, after the second month, slight moisture was observed in all the packs. This condition continued and, at the end of 8 months' exposure, condensation was observed inside all packs. One other failure in the VCI packs was noted at the end of 7 months. This was a slightly rusted aperture. The amount of rust on this component likewise did not increase after 12 months' exposure.

A slight rust condition was noted with the control group after the fourth periodic inspection. This rust condition progressively worsened until both components had become rusted at the end of the test period.

d. Heat-sealable Polyester Film in Outdoor Storage Shed - Table 4

Polyester envelopes were examined through the transparent material during the 3-year test period. No rust was detected throughout the first 33 months of exposure. After the 15th month, one pack containing an extractor was blown out of the shed and lost. The periodic examination after 27 months indicated one missing pack. This pack was subsequently found frozen in the snow on the roof. This pack was opened and the extractor was found in good condition.

At the end of 3 years, all packs were opened and examined. The two controls used were satisfactory. The VCI liners in the twelve remaining packs indicated that all had contained condensation in varying amounts. One of the extractor packages contained water; the extractor was heavily rusted. This condition was evidently due to barrier failure. Two other components, an extractor and a butt swivel, were found to be very slightly rusted. This rust was so slight that it became evident only on close examination.

It is apparent that the static humidity cabinet provided more severe testing conditions than the outdoor storage shed. In addition, the testing conditions of the outdoor storage shed were not sufficiently severe to evaluate satisfactorily the effectiveness of the VCI material in the pack.

e. Submethod 1C-1, Humidity Cabinet - Table 5

Thirteen IC-1 packs with two controls placed in the humidity cabinet were found 1 month later to vary between damp and wet. After 2 months, two packs were withdrawn. The inside of these packs was wet and the VCI liners were thoroughly soaked. The packaged rear sight covers were rusted. A third pack was opened after 3 months; this pack was found in a similarly rusted condition. After 4 months, all remaining IC-1 packs were removed. The controls were rusted. The VCI lined packs were also rusted, but not so severely as the controls. No rust was observed on the component that had been in contact with the VCI liner. It is quite possible that all the packs rusted within the first month.

f. Submethod 1C-1, Outdoor Storage Shed - Table 6

Because of the physical construction and the location of the outdoor shed, packs stored there were subjected to a natural weather cycling. During the 3 years' storage, the packages were on occasion covered with snow, dried out, rained upon, and thoroughly drenched when precipitation was accompanied by high winds. After the 4th, 5th, and 6th month, respectively, the packages were withdrawn and the

components examined. The components in three of the 4 withdrawn packs had no evidence of rust; these packs appeared to be in satisfactory condition despite the rather severe weather conditions during that time interval. The fourth package, however, had leaked and the inclosed component had rusted slightly.

After 12 months' exposure, two additional packs were opened, but no rust was found. At the 18th-month interval, a package was found on the open roof. This pack had been blown out of the outdoor storage shed during the 17th month and had been wholly exposed to the inclemencies of the weather. The component had slight rust; however, it was usable.

At the end of the 36-month test period, four packs with VCI were examined. Three of these packaged components were satisfactory, whereas the fourth was heavily rusted.

Two controls without VCI were used for the 1C-1 submethod. One control pack was blown out of the outdoor storage shed during the 9th month and was not recovered. The remaining pack was opened at the end of the 3-year test period; no rust was observed on the component.

The evaluation of the effectiveness of the VCI material with submethod IC-1 could not be made within the 3-year test period.

g. Submethod 1C-2, Humidity Cabinet - Table 7

After 1 month's exposure, light mold was observed on some wet packs. This mold condition affected all the packs within 4 months and increased in severity until the termination of the test at 12 months. At the end of 4 months' exposure, three packs containing hammers were removed from the test apparatus and examined. Mold growth was observed inside the pack and, in addition, the VCI liners were wet. None of the hammers had rust, however. A control pack which did not have a VCI liner was also examined at the same time. The packaging materials were similarly affected by moisture and heavy mold; light rust was observed on the component.

At the end of 6 months' exposure, three additional unit packs containing hammers and a front sight were examined. Although all the packs were thoroughly wet, the individual components had not rusted. The remaining control pack was also examined at this time and, as anticipated, the component was rusted (Figure 4).

The final inspection made at the end of 1 year indicated the poor condition of the barrier material. Since MIL-B-13239A material is only waterproof and not also vaporproof, the packages were tested under extremely adverse conditions, 95% relative humidity. Of the remaining six units, four were found in satisfactory condition, no rust areas were observed. The remaining two components had very slight evidence of rust.

This particular test indicated the relative value of VCI paper under extremely adverse conditions and points out that even under extended storage the added protection of VCI compensates for the use of a lower packaging submethod or material.

h. Submethod 1C-2, Outdoor Storage Shed - Table 8

The components with VCI in the unit packs were examined after the 4-month and 6-month test interval, and at the end of the 36-month test period. The control packs which did not have VCI were checked at the 6-month test interval and at the end of the investigation.

No rust was observed after 4 months' exposure and after 6 months' exposure. In addition, the control component was satisfactory. The results of the examination at the end of the test revealed only one unsatisfactory package. This was a VCI-lined pack which had become thoroughly soaked; this condition may have been due to its unfavorable position in the outdoor storage shed with respect to protection from inclement weather. This pack consisting of a harmer practically fell apart when opened, but had only light rust in one area.

1. Submethod 1C-5, Humidity Cabinet - Table 9

Heavy mold was evident on the exterior of these packs after 2 months' exposure. After 4 months' exposure, two 1C-5, two 1C-5 (modified) and one control package were removed from the test and examined. All of the packages were wet and had mold growth on both the exterior and the interior surfaces. All of the components examined had rusted after 6 months' exposure. Although the initial check was made after 4 months' exposure, it is reasonable to assume that the rust condition of all the components may have occurred at an earlier time.

After 6 months' exposure, the wet moldy condition of the containers and the liners had worsened. The fiberboard containers were saturated and delaminated. The contol and the 1C-5 (modified) packaged components were heavily rusted, whereas the components in

the 1C-5 packs had heavy rust in isolated areas only (Figure 3).

The 1C-5 and the 1C-5 (modified) containers can be considered unsatisfactory because of the extreme susceptibility of these containers to mold growth. This mold growth consequently accelerated the deterioration of the pack to the extent that preservation of the contents became unpractical.

j. Submethod 1C-5 and 1C-5 (Modified), Outdoor Storage Shed - Table 10

All packaging materials remained in good condition throughout the 36 months' exposure in the outdoor storage shed. The containers were dry after this 3-year storage, but the moisture stains indicated the wet and the dry cycling to which these containers were subjected.

The control package was opened at the end of a 4-month exposure interval; no rust was observed on the packaged component. The pack was resealed and returned to the test area. After 6 months and after 12 months, respectively, examinations showed that the components were in an excellent state of preservation. At the end of the test, the tape on the containers had started to loosen. The 1C-5 and 1C-5 (modified) pack afforded satisfactory protection for the components. The trigger guard in the control pack had slight rust on the surface. However, the limited number of controls prohibited a more complete evaluation of the effectiveness of the VCI material during the test period.

k. Submethod 1A-8, Humidity Cabinet - Table 11

The packaging material had light mold growth on the majority of the packs after the first month's exposure. One pack containing a VCI-wrapped hammer plunger, was dislodged from the test rack between the first and the second month of the test. This component was recovered at the bottom of the cabinet, entirely immersed in water. The pack, therefore, was removed from the test.

At the end of the 5th month, one pack containing a harmer spring was opened. The component was satisfactory with no evidence of rust. The following month, three control components were examined; two of these components had no rust.

These packs were examined monthly for exterior conditions and then opened after the 12th month. The barrier material was wet with mold growth on the exterior. The control packs which did not have VCI appeared damp inside. The component packed with the VCI liner was satisfactory; no rust was observed. However, slight rust was observed on all the control packs. (Fig. 5)

1. Submethod 1A-8, Outdoor Storage Shed - Table 12

After 36 months' exposure, all package exteriors were in good condition. The packaged components protected with VCI liners were without rust. Of the unlined 1A-8 packs, one was missing and a second pack had a slight amount of rust on the component.

m. Submethod 1A-15, Humidity Cabinet - Table 13

Two components, a trigger guard and a front sight, were used with this submethed in the static humidity cabinet. Although the barrier sustained light mold growth and was wet, the interiors of the packages were dry and in good condition. No rust was found on these components after 12 months' exposure.

n. Submethod 1A-15, Outdoor Storage Shed - Table 14

A trigger guard and a front sight were individually wrapped with VCI liners and stored in the outdoor storage shed.

After 36 months' exposure, the packaged components, the containers, the VCI liners, and the barrier material were in satisfactory condition.

IV. CONCLUSIONS

- a. Direct measurement or correlation is not apparent between storage time in the outdoor shed and in the static humidity cabinet.
- b. Test conditions are more severe in the static humidity cabinet than in the outdoor storage shed. However, these conditions represent only actual extremes of high temperature and high humidity.
- c. Polystyrene vials were not suitable unit packs for either the long-term shed storage or for the high humidity conditions.

IV. CONCLUSIONS - Continued

- d. The use of VCI with heat-sealable polyester material provided satisfactory protection in the humidity cabinet.
- e. The use of VCI material in submethod 1C-2 was beneficial to the packaged components in the humidity cabinet.
- f. Submethods 1C-1, 1C-5 and 1C-5 (modified) with VCI were unsatisfactory in the humidity cabinet.
- g. Submethods 1A-8 and 1A-15 provided satisfactory protection in the humidity cabinet for 12 months when VCI material was used.
- h. Testing conditions provided by the outdoor storage shed were not sufficiently severe to adequately evaluate the use of VCI material.
- i. Test results indicate that submethod 1C-2 and heat-sealable polyester packs containing VCI may be adequate for Level A Protection of specific components.
- j. Materials having a WVTR (water-vapor transmission rate) value of 0.07 grams, such as MIL-B-131, and 0.2 grams for heat-sealable polyester film provided satisfactory protection without any impairment of the efficiency and effectiveness of the VCI materials.

APPENDIX A

TABLES (14)

TAKE #1

VIAL PACK - HINIDITY CABINET

	100) I	STOPACE		TDG		Ħ	HONTHS	SE SE			
CONTROLLEM	VCI	1	7	3	4	8	9	7	80	6	10	11	12
HAMMER SPRING HOUSING	YES	w		M	SE	XX	Ř						
HAMMER SPECING	YES			#	SR	M	X						
APERTURE	TES	ងា	m	7	3	with							
APERTURE	YES	3	77	ង	ğ	with drawn							
APERTURE	YES	#	vích- dram										
				8	CONTROL								
HANGER SPRING PLINGER	QE	W	H		ğ	X	with- drawn						
HANGER SPRING PLINGER	OM	MR	M	Ħ	Ħ	Ä	víth- drem						
TRICCER PIN	OEE	#	X	*	Ħ	vích- dravn							
TRIOGRA PIN	Q	Ä	Ħ	2	#	of th- drawn							

Key to Abbreviation

TARE #2

VIAL PACK - OUTDOOR STORAGE SHED

					t	STORACE	42	TIME	ME IN	Z	MONTHS	HS									
CURPORESIT	126	1	2	3	4	5	9	7	8	9 1	10 11	112	13	711	115	116	17	18	19	8	36
HAPPER SPRING HOUSING	YES	S	တ	S	2	S	S	S	တ	S		S A	S	S	S	S	S	8	S	S	A SE
HAPPER SPRING HOUSING	YES	æ	တ	8	2	S	S	S	S	S		W S	S	8	S	တ	ဗ	8	S	S	X
HAMMER SPRING HOUSING	 YES	8	S	S	2	S	S	S	S	S		S	S	S	S	S	တ	S	လ	S	X X
APRETURE	22	တ	တ	S	Š	ဟ	SO .	S	8	S		S	S	8	S	S	S	S	S	S	MR
APERTURE	22	S	တ	S	2	S	S	8	S	S		S	S	<u>s</u>	S	S	S	S	S	S	NR
							O	CONTROLS	SIO												
HANNER SPRING PLUNGER	2	S	တ	S	2	8	S	8	S	S		S	S	S	S	S	လ	S	လ	S	LR
HANMER SPRING PLUNCER	2	S	ဟ	8	2	8	S	S	S	S		M S	S	တ	S	S	တ	တ	တ	S	Ä
TRIGGER PIN	8	S	8	S) MC	S	S	တ	S	S		S	တ	ဖ	S	S	S	S	S	S	M.
TRICCER PIN	2	S	S	8	SE SE	S	8	S	8	S		S	S	S	S	S	S	S	S	S	<u> </u>

Key To Abbreviation

S - Satisfactory
NC - Not Checked - Snow Cover
W - Wet
VSR - Very Slight Rust
LR - Light Rust
MR - Moderate Rust
MR - Moderate Rust

TABLE #5

HEAT-SEALABLE POLYESTER PACK - HUMIDITY CABINET

M E 3 爱 불 Ħ E 筹 3 별 田 萬 E Ħ 7 3 貫 W w 8 S v Ø S S Ø to LR 田 貫 3 60 00 S S 60 9 60 Ø S Ø 3 3 日 8 S S 60 Ø S S တ Ø S S 3 7 田 8 S Ø 8 8 w S 60 S Ø S 3 3 日 Ø Ø တ 60 8 Ø Ø Ø S 3 뎦 텻 Ø 8 W 8 8 8 9 Ø Ø S S Ħ 뎦 3 五 S 8 93 8 Ø Ø S Ø S Ø Ø 110 3 g SR w 8 Ø 8 တ Ø S w ທ Ø 60 CONTROL oo : 3 STORVCE 4 40 60 Ø ø 9 Ø တ Ø Ø ø 8 3 Ø 93 60 8 9 83 63 8 Ø 8 Ø 8 3 Ø တ 8 Ø Ø 8 Ø Ø 8 Ø 9 60 60 B E TES 77.5 225 27. 728 TES TES 77.5 TES TES TES R HAPPER SPRING PLUNCER HAMMER SPRING HOUSING HAPPER SPRING PLUNGER HAMMER SPRING HOUSING COMPONENT BUTT SWIVEL TRICCER PIN TRICCER PIN FIRING PIN EXTRACTOR EXTRACTOR APERTURE APERTURE TRICORD TRICCER

to Abbreviation

S- Setisfactory MR-No Rust LR-Light Rust MR-Hoderate Rust HR-Heavy Rust

TABLE #4

HEAT-SKALAMLE POLYESTER PACK - OUTDOOR STORAGE SHED

				15	STORACE		1106			Ħ	2	HOTTES									1
COMPONENTS	VCI	5	7	3	1	3	9		8	10	11	77	7	7	15	9	7	18	9	8	8
erredenos.	8	S	97	8	S	6	93		& &			8	•		0	w	8		Ø	S	Ä
EXTRACTOR	88	8	00	8	2			<u> </u>	80	- 50		89	S	•	Ø	8	S	8	8	S	NR
EXTRACTOR	5	Ø	•	•	2				8	80		S	8		S	8	S	S	တ	တ	Ä
HETPACTOR	2	99	•	93	2	*	-	•	- 10			8		••	lost	-					
HANGER SPEING	82	S	80	ø	2	S	8	S	S	8		S	8	S	8	S	89	S	S	S	Ä
HAPER SPRING BOUSTING	SE	8	•	93	2	- 8	- 8	S	8	တ		S	8	8	S	S	S	တ	တ	တ	M
APERTURE	213	8	8	ø	Ä	8	S	S	S	S		S	8	S	8	S	S	-S	S	S	MR
APERTURE	25	8	8	တ	Š	S	9	S	SS	8		S	8	S	S	S	S	S	S	S	RR
HAMER SPRING	2	07	03	87	¥	Ø	5	8	8	S		S	8	S	S		S	 S	S	S	NR
HAPER SPRING	SE	ø	89	S	2							S				S	S	S	ဟ	Ø	X.
BULT SUIVEL	res	89	S	s) MC	S	S	8	S	S		S	S	S	S	S	S	S	s	S	Z.
FIRING PIN	55	တ	တ	S	SK.	50	S	S	8	8		SS	S	S	S	S	S	S	S	S	MM
TRICCER PIN	25	8	8	8	2	•	8	s	S	8		S	S	8	S	8	S	S	S	S	NR
SAFETY LATCH	22	8	8	8)	8	S	S	S	S		S	S		8	8	S	S	S	S	MR
												3									
					I		ŀ	ł	ŀ	5	COMPLETE MANAGEMENT	3	+	+	+	}	-	-	-		
TRIGGER PIN	ğ	•	8	8	말	8	•	8	8	80		8	8	8	80	S	8	S	S	S	Ä
SAFETY CATCH	8	80	8	S	멅	80	S	<u> </u>	& &	•		S	8	S	8	S	S	S	S	S	X
Key to Abbreviation																		 		ı	

Mr. - Not Checked - Spee C.

- No Bust

TABLE 45

10-1 - MEEDITY CARINET

			STORYGE	1	The Di	I MONTHS	THS						
CONFORMER	VCI	1	2	3	*	5	9	7	8	9	91	11	12
REAR SIGHT COVER	E E	*	M	*	1								
REAR SIGHT COVER	YES	7	Z	7	-								
REAR SIGHT COVER	728	A	MA	A.A.	I								
REAR SIGHT COVER	YES	MA	A.A.	H	I								
REAR SIGHT COVER	77.8	7	M	LX.	1								
REAR SIGHT COVER	728	A	AA	Z,	ı								
REAR SIGHT COVER	YES	AS.	AA	134	ı								
REAR SIGHT COVER	TES	25.5	MA	77	R								
REAR SIGHT COVER	YES	V.V	Q	R									
REAR SIGHT COVER	YES	AUV	M										
MEAR SIGHT COVER	TES	KTA	Q	24									
REAR SIGHT COVER	YES	WIN	1										
BUTT SWIVEL PLATE	YES	HTA.	D	W	~								,
							CONTROL	و.					
CONTROL	Q	3	A	#									
CONTINUE	2	ă	LX.	3									
	_	to Abbrevietion	Eton										

Key to Abbreviation

HH - Heavy Moisture D - Demp I.R - Light Rust HR - Heavy Rust

R - Bust

VV - Very Wet SV - Slightly Wet VIM - Very Light Moisture IM - Light Moisture

- 19 -

TABLE \$6

1C-1 - OUTDOOR STORAGE SHED

						STORAGE	١	H			SECTION	2										
CONFORMERS	5	-	7	3	•	3	9	7	8		101	\vdash	12 1	13 1	14	15 1	16 17	\vdash	18 19	8		36
REAR SIGHT COVER	TES	8	8	8																		
MEAR SIGHT COVER	775	89	•	S	A	#																
REAR SIGHE COVER	YES	•	•	8	3	8	Ħ															
REAR SIGHT COVER	77.8	80	8	8	A	8	11															
REAR SIGHT COVER	TES	S	8	8	**	S	8	8	89	8	8	A	=									
REAR SIGHT COVER	778	8	8	8	33	w ₃	8	•	8	S	S	A SEE	-									
HEAR SIGHT COVER	YES	S	S)	>	S	S	S	80	S	8	7	89	3	S	Q	89	D		S	N A	NR
REAR STORT COVER	YES	8	S	S	3	S	တ	8	8	S	S	7	S	7	8	DS		D	S		M	MR
REAR SIGHT COVER	YES	a	8	8	3	S	တ		S	S	S	32	S	3	S	S Q		DS		S	3	HR
REAR STORE COVER	YES	တ	S	8	3	S	တ		တ	တ	ဖ	3	S	3	8	8		DS		8	3	M
LATCH CLIP	 77.5	8	8	S	7	S	8	s	S	- S	S	33	S	3	S	D		D	SR			
PROSE SUIVEL	TES	8	8	8	3	8	တ	8	8	80	89	A	8	3	8	D S		D 10	lost			
										3	CONTROL	ğ										
TASE REAR SIGHT	9	os	80	2	3	92	S	S	8	8	8		8	7	8	Q		S	\vdash	S	3	2
COURTE OF.	9	00	8	3	3	•	91	=	į													
			1												1		ł				l	1

Key to Abbreviation

IR - Merry Mast 8

¥ .

TARE . #1

10-2 - MENTETTY CARDIER

				STORAGE	ŀ	TDG		HOETHS					Ī
CONTONERT	Z Z	1	2	~	*	5	9	7	8	6	01	11	12
a.J. e.J.	8	7	3	1 20									
	?												
HAPEER	YES	N.No	L.Yo	L.Mo L.Mo	H.R								
HAPER	TES	L.Ko	L.Ho	L.Ho L.Ho	N.R								-
BANKR	YES	1.76	H.Yo	H.No H.No	H.No	H _D Mo	KR						
HAPER	YES	M.No	L.Yo	L. No L. No	L.Mo	H. Mo D	MR						
BANNER	YES	L.Ko	H.No	H. Mo H. Mo	H. Ko	H.Ko	H. Ho	H _Q No	Og OH	ох₽н	H.No	H.No W	N.R.
HAPER	YES	L.Yo	H.No	H.No H.No	H.Ko	H.YO	H.Mo	H. No	H. W	H.Mo	H.No W	H.No W	N. R.
HAPAER	YES	L.No	H.No	H.Yo H.Yo	H.No	H.No D	H.No	H. Mo	H, Mo	H. Mo	H. Mo	H.Mo	N.R.
HADERR	YES	M.No	N.Wo	N.Mo L.Mo	L.Yo	2.7 OG	L.Mo	H. Mo V	од∄н	H. Mo	H.Ho V	Н. Но W	N.R.
FRONT SIGHT	YES	N.No	N.Mo	N.Mo N.Mo	L.Yo	L.No	¥						
PROMT SICHT	YES	M. W	L.Yo	L. No L. No	L.Yo	L.No	L. Ho	M OM°T	М 9 Ж "]	н.жо У	H, Ho	H. Mo	S.R.
PRONT SIGHT	YES	N.Yo	L.Yo	L.Mo L.Mo	L.Yo	L.Mo W	L.Ho W	L.Mo	L. Ho	НДМО	H. No	H. Ho	S.R.
						200	CONTROL						
REAR SIGHT	8	No.	H.No	H, Yo	L. R								
NEAR SIGHT	ğ		H.76	H. Ho	H.No V	*							

Key to Abbreviation
N.Mo - No Mold
L.Mo - Light Mold
H.Mo - Heavy Mold
D - Demp

V - Wet SR - Slight Bust LR - Light Bust R - Bust RR - No Rust

TABLE #8

1C-2 OUTDOOR STORAGE SHED

VCI 1 2 3 4 5 6 7 18 VISS S						6	STORACE	B	100	ä	ā		MONTHS	E							ĺ		l
	CORPOREDIT	VCI	-	2	3	•	2	9	-				11	12	13	14	25	16	17	18	19	8	8
HES S S S S S S S S S S S S S S S S S S	HAMBER	YES	S	ă	S	S	8	Ħ															
YES S S S S S S S S S S S S S S S S S S	HAPER	YES	S	ă	တ	တ	တ																
THE SESSION ON O	HAPER	YES	8	3	S	S	8	S	S	S	S	S	3	S	3	3	3	ဟ	A	ဟ		တ	. K
THE AREA S S S S S S S S S S S S S S S S S S S	HANGR	YES	ທ ່	S	တ	S	S	S	S	S	S	S	3	S	3	3	3	တ	Α	တ	တ	တ	X.
TES S S S S S S S S S S S S S S S S S S	HAMER	YES	S	တ	တ	S	S	တ	တ	တ	S	8	3	တ	3	3	3	တ	۵,	ø,	8	တ	NR
TES S S S S S S S S S S S S S S S S S S	HAMER	YES	တ	S)	ဟ	တ	တ	တ		တ	S	ss:	; 38	S	3	3	3	တ	A	ဟ	ဟ	s.	N. H
T YES S S S S S W W W W W W S W S W S W S W	HAPPER	YES	တ	S	တ	S	တ ;	so,	့ တ	S	s)	· ·	= i	ω ,	3	3	3	S	Α.	S	ဟ	so.	Z.
T YES S NC NR S S S S S W W W W S D S T YES S NC S S S S S W S W W W S D S T YES S S NC S S S S S S S W S W W W S D S	HANKER	YES	တ	S	2	တ	S	S	တ	ဖ	S	<u>ဖာ</u>	3	Ś		3	3	S	Α.	S	S	S	SR
T YES S S S S S W W W W S D S T YES S S W S W S W W W W S D S T YES S S W S W S W S W S D S T YES S S W S W S W S W S D S	HAMER	YES	ဟ	S	ဍ				~	•••			•	~*·•	•	•-	•		,	•			
T YES S S S S S W W W S D S T YES S S NC NR T YES S NC S S NR	FRONT SIGHT	YES	တ	S	2	တ	·	S	S.	လ :	တ	 ທ		~ · ග	·· · · ·	3	3	Ś	٩	S,	S	တ	NR.
T YES S S NC NR YES S S NC S S	FRONT SIGHT	YES	တ	S	SC	S	S		တ	S	⊒ . ∽	ا م	4	- KO	3] 38 1	3	တ	۵	ω.	SO.	တ	X X
YES S NC S S	FRONT SIGHT	YES		S	ž	X		· · · •	+-			+	1	1	-	•	- 		•	•			
	REAR SIGHT	YES	S	တ	2	S	S	2						-									

		3
	-	+_
	•	-3
	<u> </u>	3
		ø
HOL		*
CONTROL		S
		S
		S
	Ä	S
		S
	S	S
	S	S
	S	S
	S	S
	တ	S
	9	8
	BASE REAR SIGHT NO	MASE REAR SIGHT

SNR

S

S

Key to Abbreviation

S - Setisfactory

- Snow Cover SR - Slieht Bu

TABLE 49

1C-5 AND 1C-5 (MODIFIED) - HURIDITY CABINET

				E	STORAGE	TIME	Ħ	NONTES					
CONTORINE	VCI	1	2	3	•	5	9	7	8	6	92	11	12
TRIGGER HOUSING	22.5	OK H	M 760	H No	SR								
TRIGGER BOUSTIC	YES	H No	N No	H No	SR								
TRIGGER HOUSING	YES	II No	H 160	H No	H Yo	H No	Ħ						
TRICCER HOUSTHG	YES	H No	H Mo	H No	он н	н жо	HR						
TRICCER HOUSING	TES	R No	H No	H Yo	H Yo	H 760	Ħ						
TRICCER HOUSING	YES	H No	H No	H No	H No	H No	H		1				
						X	5 (M	1C-5 (MODIFIED)					
TRIGGER HOUSTHG	YES	H No	H No	H No	13								
TRICCER HOUSTHG	YES	H No	H Mo	H Yo	11								
TRIGGER HOUSING	TES	н жо	H Mo	H No	H No	H No	Ħ						
TRIGGER HOUSTING	TES	H Xo	H 76	H 76	OH H	H 76	Ħ		ļ				
TRIGGER HOUSTING	YES	L No	H Xo	E X	E Ro	H 76	#						
						10.5		COMPTROS					
							- 1						
BUTT PLATE	2	91 F	H No	ON H	=								
MOTE PLATE	2	% ×	# X	H No	H No	H No	Ħ						r. sa - 1444

Key to Abbreviation

W No - No Mold

E No - Light H H No - Heavy M

TABLE #10

- OUTDOOR STORAGE SHED

1C-5 AND 1C-5 (MODIFIED)

X X SR ጸ Z Ħ Z Z KK N. K X S 8 S Ø ຜ Ø S S S S S Ø S S Ø S S S S တ တ S 18 S S S w S S S S S S S 11 **A** 9 A **A** A S S S S S S S S 91 S S ဟ 15 S 3 3 3 3 3 Ø S S S S 14 S S S Ø S S S S Ø S Ø 3 3 3 3 3 3 13 3 3 3 3 3 1C-S (MODIFIED) 風 MORTHS 0 11 12 S Ø Ø S Ø S Ø S S S 1C-5 CONTROL Ø S S S S Ø S ø Ø S S 01 Ø တ Ø S S Ø S S 8 S S Ø 70 49 S S S S () S S တ 6 ø S S S Ø S S ∞ Ø Ø v S Ø S S Ø S S w S S ø S S S 60 Ø • တ Ø Ø Ø 를 Ø 5 Ø Ø Ø S S Ø 60 S S Ø S S 8 Ĕ S S 03 S 4 S Ø S 8 S တ S Ø 9 Ø S S S S Ø Ø Ø 60 60 9 Ø 60 10 9 8 Ø Ø Ø ~ 80 8 Ø 60 S Ø .65 9 Ø S Ø Ø 93 60 Ø S S 728 YES TES YES TES TES 77.8 25.5 YES 222 TES 욡 TO. HOUSING HOUSTING HOUSTING HOUSTING HOUSTING HOUS THG HOUSTING HOUS INC HOUSTING HOUS THE HOUSTING HOUS INC GIVE TRICCER CUARD CORPOREDIT TRIGGER TRIGGER TRICCER TRICCER TRICCER TRICCER TRICCER TRIGGER TRICCER TRICCER TRIGGER TRIGGER TRICCER

Key to Abbreviation
R - Resealed

Resealed MR - No hu Satisfactory W - Wet Slight Rust D - Damp

- 24 -

TABLE \$11

1A-8 - HALDITY CABINET

			es es	STORACE	THE	Ħ	HONTHS	8					
CONTRON	ACI	1	2	3	4	5	9	7	8	9	10	11	12
HAPER SPRING	TES	S.Mo.	H.No	H.No	M, C.	H.R.							- I
HAPER SPRING	YES	S.No	H.No	H.No	M.C.	Mold	Mold	Mold	Mold	plox	Mold	Mold	M. R.
HAPER SPRING	YES	S	Lost										
-							CONTROL	ی					
CAICH OPERATING NOD	Q.	L.Mo	L.Yo	L.Yo	M.C.	L.No	Ä						
CATCH OPERATING ROD	2	1. Yo	L.76	L.No L.No	M.C.	L.Yo	Æ						
CATCH OPERATING ROD	Q	L.Yo		L.No	Z	N.C. L.Mo	MA						
POLLOWER	Q.	တ	¥er.	F	Z.C.	L.Mo	Lost						
HAMER SPRING HOUSING	2	S	L.Yo	L.Mo	E.C.	L.Mo	1.Yo	1.76		L.Yo	L.Mo L.Mo L.Mo L.Mo	L.Mo	S
HAMER SPRING PLUNCER	Q	L.Yo	L.Mo	L.Yo	X.C.	L.Yo	L.Mo L.Mo	1.86	L.Yo	L.Mo L.Mo L.Mo	L. Mo	L.Mo	as:
HAPPER SPRING PLUNCER	9	L.Yo	L.No	L.Mo	N.C.	L.Yo	L.Mo	L.Yo	L.Mo	L.Mo	Н.Мо Н.Мо	H.Mo	SR
ARH POLLOWER	2	L.No	L.Yo	L.No	Z.C.	L.Mo N.C. L.Mo L.Mo	L.Yo	L. Mo	L.Yo	L.Ko	H. No	H. Mo	a S
ARM POLLOWER	2	L.Yo	L.Yo	L.Mo L.Mo	M.C.	L.Yo	L.Mo L.Mo	L.Yo	L.Mo . L.Mo	L.Mo	H.Mo	H.Mo	SR
Key to Abbreviation													

S.Mo - Slight Mold
L.Mo - Light Mold
H.Mo - Beavy Mold
S. - Satisfactory
N.C. - Not Checked - Snow Cover
N.R. - No Rust
S. - Slight Rust
N.R. - Moderate Rust

TABLE #12

SHED 1A-8 - OUTDOOR STORAGE

COULTEOL S S S N N N N N N N N N N N N N N N N	COMPENENT	ACI	_	2	<u></u>	4	2	9	1	80	6	2	1111	12 1	13	14	15.1	16 1	17 18	10	\vdash	35 06	T
TGHT TES S S NC NC S S S S N N S N S N S N S N	HAPPER SPRING HOUSING	SES	-	on on	8	2	S	E	1	+	┼─	 	-	 	 			+	_	 	┼	+	T
TCHT YES S S NC S S S S S S S S S	TRIGGER	77.5	ø	8) M	SE SE	S	S	S				32		_		38	_			3	N	
PERATTING NO S S S NC S NR C C C C C C C C C C C C C C C C C C	REAR SIGHT	YES	S	S) MC	S	S	S								132			-	3	Z	
PERATING NO S S NC S NR PERATING NO S S S NC S NR ATE NO S S S NC S S S S N S S S N S N S N S N											ಶ	T A	8										
PERATING NO S S S NC S NR	CATCH OPERATING ROD	8	ø	8	တ	2	8	ă			-	 		-	-	-	-	-	_		-		
PRRATTING NO S S NR S S S N N <th< th=""><th>CATCH OPERATING</th><td>2</td><td>8</td><td>တ</td><td>တ</td><td>2</td><td>S</td><td>× ×</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td> </td><td> </td><td></td><td></td><td></td><td>-</td><td></td><td></td></th<>	CATCH OPERATING	2	8	တ	တ	2	S	× ×													-		
ATE NO S S S NC S S S S S W S W S W S W S W S W S W W W S W	CATCH OPERATING	Ş	S	S	8	2	8	N.								-							
ATE NO S S S NC S S S S S W S W S W S W S W S W S W W W S W	PLINGER	QK QK	S	S	S	2	S	8	တ	S				S							3	VS	M
R. NO S S S S S S F S F S F	BUTT PLATE	Q	တ	S		35	တ	S	S	S			72	S				-			3	N N	~
LOWER NO S S S S S S F <th>POLLOWER</th> <td>9</td> <td>S</td> <td>8</td> <td>S</td> <td>2</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td></td> <td></td> <td>130</td> <td>S</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>73</td> <td>NR</td> <td></td>	POLLOWER	9	S	8	S	2	S	S	S	S			130	S							73	NR	
INO S S S S S S S S D S D S S W NO S S S S S S S S D S S S N S N S N S N S N S N S N S N S N	ARM POLLOWER	NO	Ø	8		3	တ	တ	S	S			,,,,	S							3	N.	
NO S S S S S S S W S W S W S D S S W	TRIGGR	Q	တ	တ		Š	တ	8	S	S				8							3	- E	
	TRIGGER	8	တ	ø		2	w	S	8	Ø				S							3	10	

- Not Checked - Snow Cover - Wet Key to Abbreviation

MC - Not Checked - Si
W - Wet
D - Demp
VW - Very Wet
S - Satisfactory
VSR - Very Slight Rusi
MR - Mo Rust

TABLE #13

1A-15 - HUMIDITY CABINET

			U	CTODACE	TTK		SHIPO	E					
			2		١	l	l		ľ	•	•	-	-
THE WOOD OF	VCT	-	6	~	4	·	9	_	×	6	3	77	71
COMPONENT	12.	1	3	,	•								Z.
	000	U	U	v	ט	S	NC NC	S	s	S	S	S	0
TRICGER GUARD	153	?	2	,									2
	340	U	X	1 Ko 1. Ko	N C	L XO	NC	L Mo	NC L Mo L Mo	1 70	L MO L MO L Mo	L Mo	D
FRONT SIGHT	153		3										
		-											
See hard a become of the													

Key to Abbreviation

- Snow Cover Satisfactory
Not Checked .
Light Mold
Dry
No Rust S NC L Mo D NR

TABLE #14

1A-15 - OUTDOOR STORAGE SHED

						ผ	STORAGE	3	TUR	角	ä	3	CONTHS								Ì		
COMPONENT	:	VCI	1	7	٣	4	2	9	7	æ	6	10	11	12	13 1	14 15	.5	16 17 18	7 1	8	6	2	36
TRIGGER	HOUSING	YES S	တ	တ	တ	S	လ	တ	တ	S	တ	S	တ	v	10	တ	တ	တ	·		 	: 	NR
TRIGGER HOUSING		YES S	S	လ	S	S	တ	တ	S	S	S	S	တ	တ	- s	S	S	S	S	S	တ	ro	NR

Key to Abbreviation

S - Satisfactory NR - No Rust

APPENDIX B

PHOTOGRAPHS

19-058-99/ORD-60	Figure 1	Outdoor Shed Exposure Site With Doors Open
19-058-96/ORD-60	Figure 2	Exterior Condition of Packages After 6 Months Storage Group A - Humidity Cabinet Group B - Outdoor Shed
19-058-95/ORD-60	Figure 3	View Showing Condition Of Packaging Materials In 1C5 Packs After 6 Months Storage Group A - Humidity Cabinet Group B - Outdoor Shed
19-058-97 /ORD-60	Figure 4	Components and Packaging Materials After 6 Months Storage Group A - Humidity Cabinet Group B - Outdoor Shed
19-058-98/ORD-60	Figure 5	Packages Taken From Humidity Cabinet After One Year Storage
19-058-1356/ORD-60	Figure 6	Method 1C2 Packages After Three Years Exposure
19-058-1357/ORD-60	Figure 7	Method 1Cl Packages After 3 Year, Exposure. Item At Extreme Right Sustained Heavy Rust
19-058-1358/ORD-60	Figure 8	Packages As Removed After Three Years Exposure In Outdoor Shed



19-058-99/ORD-60

SPRINGFIELD ARMORY


OUTDOOR SHED EXPOSURE SITE WITH DOORS OPEN




19-058-96/ORD-60

SPRINGFIELD ARMORY


EXTERIOR CONDITION OF PACKAGES AFTER 6 MONTHS STORAGE GROUP B - Outdoor Shed GROUP A - Humidity Cabinet



GROUP B - Outdoor Shed VIEW SHOWING CONDITION OF PACKAGING MATFRIALS SPRINGFIELD ARMORY IN 1C5 PACKS AFTER 6 MONTHS STORAGE. GROUP A - Humidity Cabinet 19-058-95/ORD-60



COMPONENTS AND PACKAGING MATERIALS AFTER + MONTHS STORAGE GROUP B - Outdoor Sted CROWL A - Hamidity Cabinet -45 -15 ORD-60



PACKAGES TAKEN FROM HUMIDITY CABINET AFTER ONE YEAR STORAGE


SPRINGFIELD ARMORY

19-058-98/ORD-60

25 Jan 1960

SPRINGFIEL

ORD-60



ELD ARMORY - ORDNANCE CORPS

Date: 10 November 1960 Pro

KETHOD ICI CKAGES AFTER 3 YEARS EXPOSURE. ITEM AT EXTREME RIGHT SUSTAINED HEAVY RUST.



SPRINGFIELD ARMORY - ORDNANCE CORPS

DISTRIBUTION

·	Copies
Office of the Director of Defense The Pentagon, Room 3D-1085 ATTN: Mr. J. C. Barrett, Research & Engineering Washington 25, D. C.	1
Commander Armed Services Technical Information Agency ATTN: TIPDR Arlington Hall Station Arlington 12, Virginia	10
Solid Propellant Information Agency Applied Physics Laboratory The Johns Hopkins University Silver Spring, Maryland	1
Commanding General Army Materiel Command Bldg. T-7 (Room 817) Department of the Army Washington 25, D. C.	1
Commanding General Aberdeen Proving Ground ATTN: Coating & Chemical Laboratory (1) Technical Library (1) Aberdeen, Maryland	2
Headquarters U.S. Army Mobility Command 28251 Van Dyke Avenue Centerline, Michigan	2
Commanding General U. S. Army Weapons Command ATTN: AMSWE-RD (1) AMSWE-ISC(1) Rock Island, Illinois	2

	Copies
Commanding General U.S. Army Ballistic Missile Command Redstone Arsenal, Alabama	2
Commanding Officer Frankford Arsenal ATTN: ORDBA-1330 (1) Library-0270 (1) Philadelphia 37, Pa.	2
Commanding Officer Ordnance Materials Research Office Watertown Arsenal ATTN: RPD Watertown 72, Mass.	1
Commanding Officer Picatinny Arsenal ATTN: Plastics & Packaging Lab Dover, N. J.	1
Chief Plastic Technical Evaluation Center Picatinny Arsenal Dover, N. J.	1
Commanding Officer Rock Island Arsenal ATTN: Materials Section, Laboratory Rock Island, Illinois	1
Commanding Officer Watertown Arsenal ATTN: ORDBE-LX Watertown 72, Mass.	1
Commanding Officer Watervliet Arsenal ATTN: ORDBF-R Watervliet, New York	1

	Copies
Commanding General U.S. Army Ordnance Special Weapons and Ammunition Command ATTN: C. H. Staley Dover, New Jersey	1
Commanding Officer U. S. Army Environmental Health Laboratory Army Chemical Center, Maryland	1
Commanding General U. S. Army Chemical Warfare Laboratories ATTN: Technical Library Army Chemical Center, Maryland	1
Commanding Officer Diamond Ordnance Fuze Laboratory ATTN: ORDTL-06.33 Connecticut Avenue and Van Ness St., N. W. Washington 25, D. C.	1
Commanding Officer Engineer R&D Laboratory ATTN: Materials Branch Ft. Belvoir, Virginia	1
Commanding General Quartermaster R&D Command ATTN: Clothing and Organic Materials Division Natick, Massachusetts	1
Commanding Officer Army Prosthetics Research Laboratory ATTN: Dr. F. Leonard Forest Glen, Maryland	1
Headquarters U.S. Army Signal R&D Laboratory ATTN: Materials Branch, Louis Reiss Fort Monmouth, N. J.	1

	Copies
Commander Army Research Office	1
3045 Columbia Pike ATTN: Mr. A. Fan Arlington 12, Virginia	
Commanding Officer U.S. Army Research Office (Durham) Box CM Duke Station Durham, North Carolina	1
Chief of Research and Development U.S. Army Research and Development Liaison Group ATTN: Dr. B. Stein APO 757, New York, N. Y.	1
Commanding General White Sands Proving Ground Las Cruces, New Mexico	1
Commanding General Aberdeen Proving Ground ATTN: Technical Library, ORDBG-LM, Bldg 313 (2) DPS, Branch Library #3, Bldg 400 (2) Aberdeen, Maryland	4
Commanding Officer U. S. Army Ordnance Training Command ATTN: ORDHB-CR-C Aberdeen Proving Ground, Maryland	1
Commandant U. S. Army Ordnance School ATTN: USAOS Technical Library (1) Non-Resident Training Division (1) Aberdeen Proving Ground, Maryland	2

	Copies
Chief, Bureau of Naval Weapons Department of the Navy	1
ATTN: RMMP	
Room 2225, Munitions Building	
Washington 25, D. C.	
Department of the Navy	1
Office of Naval Research	
ATTN: Code 423	
Washington 25, D. C.	
Dept. of the Navy	1
Bureau of Ships	
ATTN: Code 344	
Washington 25, D. C.	
Department of the Navy	1
Special Projects Office	
ATTN: SP 271	
Washington 25, D. C.	
Commander	1
U.S. Naval Ordnance Laboratory	
ATTN: Code WM	
White Oak, Silver Spring, Maryland	
Commander	1
U.S. Naval Ordnance Test Station	
ATTN: Technical Library Branch	
China Lake, California	
Commander	1
U.S. Naval Research Laboratory	
ATTN: Technical Information Center	
Anacostia Station	
Washington 25, D. C.	
Commander	1
Mare Island Naval Shipyard	
ATTN: Rubber Laboratory	
Vallejo, California	

	Copies
Commanding Officer Bureau of Naval Weapons Technical Liaison Office ATTN: Navy Liaison Office, Bldg. 305	1
Aberdeen Proving Ground, Maryland U. S. Air Force Directorate of Research and Development	1
ATTN: Lt. Col. J. B. Shipp, Jr. Room 4D-313, The Pentagon Washington 25, D. C.	
Wright Air Development Division ATTN: ASRCEE-1 (1) WWRCO (1)	3
Materials Central (1) Wright-Patterson Air Force Base, Ohio	
ARDC Flight Test Center ATTN: Solid Systems Division, FTRSC Edwards Air Force Base, California	1
AMC Aeronautical Systems Center ATTN: Manufacturing & Materials (1) Technology Division, LMBMO (1) Wright-Patterson Air Force Base, Ohio	2
National Aeronautics and Space Administration ATTN: Mr. R. V. Rhode (1) Mr. G. C. Deutsch (1) Washington, D. C.	2
George C. Marshall Space Flight Center National Aeronautics and Space Administration ATTN: M-S&M-M Huntsville, Alabama	1
Army Reactor Branch Division of Reactor Development Atomic Energy Commission Washington 25, D. C.	1
U.S. Atomic Energy Commission Office of Technical Information Extension P.O. Box 62 Oak Ridge, Tennessee	1

	Copies
Jet Propulsion Laboratory California Institute of Technology ATTN: Dr. L. Jaffe 4800 Oak Grove Drive Pasadena, California	. 1
George C. Marshall Space Flight Center ATTN: M-F&AE-M Huntsville, Alabama	1
Prevention of Deterioration Center National Academy of Science National Research Council 2101 Constitution Avenue Washington 25, D. C.	1
Director, National Bureau of Standards Department of Commerce Washington 25, D. C.	2
Commanding Officer Red River Arsenal ATTN: ORDKJ Texarkana, Texas	1
Commanding Officer Chicago Quartermaster Depot Food & Container Institute for Armed Forces 1819 West Pershing Road Chicago 9, Illinois	1
Commanding Officer Rossford Ordnance Depot Toledo, Ohio	1
Commanding Officer Letterkenny Ordnance Depot ATTN: ORDKE-I Chambersburg, Pennsylvania	1

	Copies
Commanding Officer Anniston Ordnance Depot Anniston, Alabama	1
Chief, Container Materials Section Headquarters AMC - MCMPXT Wright-Patterson Air Force Base ATTN: Command Packaging Office Dayton, Ohio	1
Commanding Officer 831st AF-SPD ATTN: Inspection Department Shelby, Ohio	. 1
Commandant, Marine Corps U.S. Headquarters ATTN: Packaging Engineer - Code CSM Washington 25, D. C.	1

2. Carrosion Inhibitors 3. Barrier Materials 1. Packaging An investigation was made to evaluate the suitability of using various submetched with volatile-corrosion-inhibitor-treated materials in the peckaging of small arms components. Fackages were stored under two conditions: (1) in an outdoor shed to simulate minimum warehouse storage and (2) in a static hundidity cabinet to simulate tropic storage, heart-seatable polysets film with volatile-corrosion-inhibitor immewrap provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that peckaging submetched other preservatives. Test procedures are described and results given. Springfield Armory, Springfield, Mass.
INVESTIGATION OF PACACING METHODS AND SUBMETHODS WITH VOLATILECORROSION-INHIBITOR IERAIED MAIRELALS, by G. Pributsky, Tech Rept
SA-TRZO-2313, 1 Aug 62, 45 pp incl illus. Unclassified report. Monlisite' distribution. 2. Corrosios Inhibitors 3. Berrier Materials 1. Packaging An investigation was made to evaluate the suitability of using various submethods with volatile-corrosion-inhibitor-treated materials in the peckaging of small arms components. Packages were stored under two conditions: (1) in an outdoor ahed to simulate minimum warehouse storage and (2) in a static hamidity cabinet to simulate tropic storage. Heat-smalable polyseter film with volatile-corrosion-inhibitor innervrap provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that packaging submethods other than those specified in MiL-1-8574 can be satisfactorily used with VCI preservatives. Isst procedures are described and results given. Springield Armory, Springield, Mass.
INVESTIGATION OF PACAGENCE METHONS WITH VOLATILECORRESSOR-INSTITUTE INVESTMENTS, by G. Pributsky, Tech Rept.
SA-IRZO-2313, 1 Aug 62, 45 pp incl illus. Unclassified report. Monlimite' distribution.

An investigation was made to evaluate the suitability of using various submethods with volatile-corrosion-inhibitor-treated materials in the packaging of small are components. Packages ware stored under two conditions: (1) in an outdoor shed to simulate minimum werehouse storage and (2) in a static hundledty cabinet to simulate tenioning the statistic the statistic hundledty cabinet to simulate trongs reported to provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that packaging submethods other than those specified in HiL-1-8514 can be satisfactorily used with VCI preservatives. Test procedures are described and results given. Springfield Armory, Springfield, Mass.
INVESTIGATION OF PACAGAINC METHODS AND SUBMETHODS WITH VOLATILECORDOSION-INHIBITOR INFAIRD MATERIALS, by G. Pributsky, Tech Rept
SA-TRZO-2313, 1 Aug 62, 45 pp incl illus. Unclassified report. Nonlimite distribution.

2. Corrosion Inhibitors

1. Packaging

Acession

5

2. Correston Inhibitors Marrier Materials

ë

Unclassified report.

Monitaite distribution.

An investigation was made to evaluate the auitability of using various submatched with volatile-corrosion-inhibitor-treated materials in the packaging of small arms components. Packages were stored under two conditions: (1) in an outdoor ahed to simulate minimum warmhouse storage and (2) in a startic humidity cabins to simulate tropic storage. Heat-smalable polymater film with volatile-corrosion-inhibitor inmervap provided satisfactory proceetion in the humidity cabinet for one year. Beaults of this investigation indicate that packaging submatches other than those specified in MIL-1-8574 can be satisfactorily used with VCI preservatives. Test procedures are described and results given.

1. Packaging

Springfield Armory, Springfield, Mass.
INVESTIGATION OF PACKAGING METHODS AND SUMMETHODS WITH VOLATILE-CORROSION-INHIBITOR IRRAID MATERIALS, by G. Pributsky, Tech Mapt. SA-TRZO-2313, 1 Aug 62, 45 pp incl illus.

3

3. Marrier Materials

Packaging Springiseld Armory, Springiseld, Mass.
INVESTIGATION OF PACKAGING METHODS AND SUBMETHODS WITH VOLATILECORNOSION-INHIBITOR IREAIED MATERIALS, by G. Pributsky, Tech Mapt.
SA-TRZO-2313, 1 Aug 62, 45 pp incl illus. Acession

2. Corrosion Inhibitors 3. Marrier Materiale Unclassified report. Nonlimite? distribution.

An investigation was made to evaluate the suitability of using various submetheds with voistile-corrosion-inhibitor-treated materials in the packaging of small arms components. Packages were stored under two conditions: (1) in an outdoor ahed to simulate minimum warehouse storage and (2) in a static humidity cabinet to simulate tropic storage. Hear-mealable polyester film with volatile-corrosion-inhibitor innerrap provided estafafactory procection in the humidity cabinet for one year. Results of this investigation indicate that packaging submetheds other than those specified in MILI-1-8574 can be satisfactorily used with VCI preservatives. Test procedures are described and results given.

2. Correcton Inhibitors 1. Packaging Springfield Armory, Springfield, Nass.
INVESTIGATION OF PACKAGING NETHODS AND SUMMETHODS WITH VOLATILE.
CORROSION-INHIBITOR IRRAID MAIRIALS, by 6. Pributshy, Tech Mape
SA-IR20-2313, 1 Aug 62, 45 pp incl illus. 3

Moo'imite' distribution.

An investigation was made to evaluate the suitability of using various submathbuds with volatile-corrosion-inhibitor-treated materials in the packaging of small area components. Packages were stored under two confitions: (1) in an outdoor abed to simulate minimum warshouse storage and (2) in a static humidity cabinet to simulate tropic storage. Heat-sealable polyester film with volatile-corrosion-inhibitor innerrap provided estisfactory procection in the humidity cabinet for one year. Busults of this investigation indicate that packaging submethods other than those specified in HIL-1-8574, can be satisfactorily used with VCI preservatives. Test procedures are described and results given.

1. Packaging Springfield Armory, Springfield, Mass. INVESTIGATION OF PACAGENE AFTHOOD AND SUBMETHOOD WITH VOLATILE-CORNOSION-INIBITION INEATED MATERIALS, by G. Pributsky, Tech Rept SA-TRZO-2211, 1 Aug 62, 45 pp incl illus.

Unclassified report.

Corrosion Inhibitors

3. Barrier Materials

Monlimite distribution.

submethods with volatile-corrosion-inhibitor-treated meterials in the packaging of small arms components. Packages were stored under two conditions: (1) in an outdoor shed to simulate minimum werehouse storage and (2) in a static humidity cabinet to simulate tropic storage. Hear-smalable polyester film with volatile-corrosion-inhibitor immervap provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that packaging submethods other than those specified in Hill-1-6574 can be satisfactorily used with VCI preservatives. Test procedures are described and results given. An investigation was made to evaluate the suitability of using various

3

Springfield Armory, Springfield, Nass.
INVESTIGATION OF PACAGOIN WITHOUS WITH VOLATILECORROSION-INHIBITOR INEATED MATERIALS, by G. Pributeky, Tech Mapt
SA-TRZO-2213, 1 Aug 62, 45 pp incl illus.

Unclassified report.

2. Corresion Inhibitors

1. Packaging

3. Marrier Materiele

Monlimite distribution.

3. Berrier Materiale

Unclassified report.

An investigation was made to evaluate the suitability of using various submethods with volatile-correction-inhibitor-treated materials in the peckaging of small arms components. Packages were stored under two conditions: (1) in an outdoor shed to simulate minimum warehouse storage and (2) in a static humidity cubiner to simulate tropic storage, provided satisfactory protection in the humidity cabinet for one year. Results of this investigation indicate that peckaging submethods other than those specified in Nil-1-55% can be satisfactorily used with VCI preservatives. Test procedures are described and results given.